



Issue 2 changes; six 5.2mm holes
moved 47mm to left

**Index, F4 MKII Rear Serv.
PI589, Issue 2, 22-03-07
Pertronic Industries Ltd**