

NOTES

- 1. STI-8130 consists of (1) STI-8100 cover & (1) STI-8101 Spacer including all standard mounting hardware.
- 2. Installer shall follow NFPA 72 National Fire Alarm code (protective signalling systems) for installation testing and maintenance.
- 3. Do not paint this product. Painting may obstruct the flow of the smoke to the detector.
- 4. When installing STI-8100 guard with Siemens detectors, sensitivity adjustment is mandatory. See Siemens' detector install sheet.
- ▲ WARNING: This product can expose you to chemicals including Dichloromethane, which is known to the State of California to cause cancer, and Bisphenol A (BPA), which is known to the State of California to cause birth defects or other reproductive harm. For more information go to **www.P65Warnings.ca.gov**.

Three year warranty or a one year limited warranty (from date of purchase) on most products. See website for details. Electronic warranty form at **www.sti-usa.com/wc14**.

APPROVALS

STI-8100 & STI-8130 GUARDS

Sentrol smoke detector models: 611UD, 612UD, 721UD, & 731UD under 300 Fpm. STI-8100 GUARD ONLY

STI-8100 UL Listed No. S3504 for use with the following smoke detectors: System Sensor Models 2251, 22517, 2251B, 2251TB, 2251TM, 2251TMB, 2251BR, 2551, 2551T, FTX-P1, FCI Models ASD-PL, ASD-P, ASD-PH, ASD-PTL, ASD-FILTREX, ASD-FILTREXF, MCS-ACCLIMATE, ASD-PL2, ASD-PL2F, ASD-PTL2F, MCD-ACCLIMATE2, MCS-ACCLIMATE2F, ASD-PL2FR, Secutron Models MRI-2251, MRI-2251B, EST Models 2251F, 2251FB, Mircom Models MIX-2251, MIX-2251B, Intelligent Systems Model ISL 2251, JCI Model 2951J, ADT Model 2951ADT, Fire-Lite Model SD355, Gamewell Model SS-P, Honeywell Models TC806B1076, TC806B1001 under 300 Fpm, Notifier Model FSP-751, FSP-851 and Siemens Models PE-11, FP-11, FPO-11, HFP-11, HFPO-11, DB-11.

INSTALLATION OF STI-8100/STI-8130 SMOKE DETECTOR DAMAGE STOPPER®

All specifications and information shown were current as of publication and are subject to change without notice.

8100IS MAR2017